






**FIG. 1**


**FIG. 2****FIG. 3**

**FIG. 4**


SCRATCH PREVENTION PANEL STRUCTURE



**FIG. 5** (PRIOR ART)


CONVENTIONAL PANEL STRUCTURE



**FIG. 6****FIG. 7**

TURNING-OVER OCCURS  
AT VERTICAL SLIT PORTION



**FIG. 8** (PRIOR ART)**FIG. 9**

**FIG. 10**

**FIG. 11****FIG. 12**

**FIG. 13**